VISIBLE EMISSION NOTATIONS			7			
Inspector: Ted Compt	<u></u>					
Date of Inspection:						
Shift: 1st Shift or 2nd Shift	Time:			Comments		
Unit 	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments		
Visible Emission From Shaker	Na					
Visible Emission From Discharge Conveyor System	Nov	Castleman and the castle and the cas			!	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





VISIBLE EMISSION NOTATIONS		
Inspector: Jeremy Hardin		
Date of Inspection:		
Shift: 1st Shift or 2nd Shift	Time: 6,000m	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>	Comments
Visible Emission From Shaker	normal .	
Visible Emission From Discharge		
Conveyor System	Aronnal	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
 cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
 or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			1		
Inspector: Chemu Sa	ucedo		-		
Date of Inspection: 8/3/15					
Shift: 1st Shift or 2nd Shift	Time:	515 AM		Comments	ir)
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL			SOMMERICS The Property of the	119
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Noamal	Comment			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			7	
Inspector: Chema Sa	veeds		_	
Date of Inspection: 8/4/15			_	
Shift: 1st Shift or 2nd Shift	Time:	530 AM	Lating 2 (1981)	
Unit-	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	
Visible Emission From Shaker	Normen			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			1		
	<u>L</u>				
Date of Inspection: 5-5	-18				
Shift: 1st Shift or 2nd Shift	Time:	5103 Am	Comm	Sorte !	
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL			IERIS.	
Visible Emission From Shaker	Apper	repaire!			
Visible Emission From Discharge Conveyor System	, vol				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			7		
Inspector:	olar				
Date of Inspection: 6/5/2	95				
Shift: 1st Shift or 2nd Shift	Time:	5:00pm	Co	mments	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>				
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					,
Inspector: Paul Call					
Date of Inspection: 8-6-15					
Shift: 1st Shift or 2nd Shift	Section Comments Comments (Section Comments (Section Comments (Section Comments Comments (Section Comments Comm	-00 AW	Con	nments	
Unit	Visual Inspection NORMAL				
	or <u>ABNORMAL</u>	(C) (2) (3) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4			
Visible Emission From Shaker	Ahnor				
Visible Emission From Discharge Conveyor System	Nor				wn

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NOTATIONS						
Inspector: L ben	lolad					
Date of Inspection: 866	215				•	
Shift: (1st Shift) or 2nd Shift	Time:	5.00pm	+			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			omments		
Visible Emission From Shaker	Norm					
Visible Emission From Discharge Conveyor System	Norm					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Vand Lad	Annual Control of the				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	/ Time:	4288 MV	Commer	nts	N. H. Carlotte
Unit	Visual Inspection <u>NORMAL</u>				
	or <u>ABNORMAL</u>	The state of the s			
Visible Emission From Shaker	AT NOV				
Visible Emission From Discharge Conveyor System	W				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector:	dal			
Date of Inspection: S/7/2	012			
Shift: 1st Shift or 2nd Shift	Time:	S:ODP-	Comments	
Unit	Visual Inspection NORMAL			
	or <u>ABNORMAL</u>	Angelise de la company de La company de la company de La company de la c		
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Norm			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





VISIBLE EMISSION NOTATIONS	<i>i</i>				
Inspector: Ted Conf.	f and				- - • ነ
Date of Inspection: 8/8/15	Time:	1000			The state of the s
Shift: 1st Shift or 2nd Shift			Con	nimenis	
Unit	Misuell "" Imspediten		Programmes Programmes		
	<u>MORMAL</u>				
	<u>ABNORIMAL</u>				
Visible Emission From Shaker	Nov				
Visible Emission From Discharge	1		and the state of t		
Conveyor System	100/		- in operation, not cour	nting start up ro shut dow	1

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
- or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS	1				
Inspector: Ted Copt	<u>ta</u>				
Date of Inspection: 8/9//5	Time:	5 0 ml	10 T 0 T 0 T 0 T 0 T 0 T 0 T 0 T 0 T 0 T		
Shift: 1st Shift or 2nd Shift			Co.	mimeny	
<u> </u>	Inspection ::				
	OI T				The state of the s
5 Shaker	ABNORIWAL				
Visible Emission From Shaker	No				
Visible Emission From Discharge Conveyor System	No		a in operation, not cou	inting start up ro shut d	own

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Paul Lave	,				
Date of Inspection: 8 10-13					
Shift: 1st Shift or 2nd Shift	Time:	5:00 AV	Commo	ents	
Unit	Visual Inspection <u>NORMAL</u> or				
	<u>ABNORMAL</u>		A CONTROL OF THE STATE OF THE S		Market and the contractions and the contraction of
Visible Emission From Shaker	ABrer				
Visible Emission From Discharge Conveyor System	NOC				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: De Mulc	undti					
Date of Inspection: 8/10/20	015					
Shift: 1st Shift or 2nd Shift	Time:	<u>>:00fm</u>	Comi	ments		
Unit	Visual Inspection NORMAL					
	or <u>ABNORMAL</u>	E E E E E E E E E E E E E E E E E E E				
Visible Emission From Shaker	Norm					
Visible Emission From Discharge Conveyor System	Norm				own	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS						
Inspector: Paul Lark						
Date of Inspection:						
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm	Con	nments	19 19 19 19 19 19 19 19 19 19 19 19 19 1	
Unit	Visual Inspection <u>NORMAL</u> or					
	<u>ABNORMAL</u>		1			
Visible Emission From Shaker	ABrox	Cepan	200			
Visible Emission From Discharge Conveyor System	nor				t down	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	£				
Inspector:	Johnard	TT.			
Date of Inspection:	Time:				
Shift: 1st Shift or 2nd Shift		<u>9:00pm</u>	Con	nments	Total form of the second state of the second s
Unit	Visual Inspection	Partition like a second of the second			
	<u>NORMAL</u>			us for the Section of	
	or <u>ABNORMAL</u>	1990 (2) (2)	Section 1999		
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS		A STATE OF THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN COLUM	1		
Inspector: Damian Sa	LAS DY				. A. I.
Date of Inspection: $8-12-15$			_		
Shift: 1st Shift or 2nd Shift	Time:	51m	Co	mments	
Unit	Visual Inspection		Application of the control of the co		
	NORMAL		The second secon		in the second se
	or ABNORMAL		Sept. Activities (Control of Control of Cont		
Visible Emission From Shaker	Nor	Agreen-			
Visible Emission From Discharge	Nor	² -andrewsparence			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Damian Sal	7				i i
Date of Inspection: $g - 13 - 15$	Time:				
Shift: 1st Shift or 2nd Shift Unit	Visual	Spm	nments		
7 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Inspection NORMAL				
	or <u>ABNORMAL</u>	1000			_
Visible Emission From Shaker Visible Emission From Discharge	Ny	'ear'			
Conveyor System	Not		in a start up ro shut d	down	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					18
1	45 Tr				
Date of Inspection: 8-14-15		and the second s			
Shift: 1st Shift or 2nd Shift	Time:	5pm	Comme	ents.	
Unit	Visual Inspection			The second secon	
	NORMAL			Bernard State of Stat	
	or A <u>BNORMAL</u>	Taring the second secon			
Visible Emission From Shaker	Nor	e/application.			
Visible Emission From Discharge Conveyor System	Nov			chut down	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			٦	
Inspector: Paul Lav				
Date of Inspection: 8-1515				
Shift: 1st Shift or 2nd Shift	Time:	5:00 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comment	
Visible Emission From Shaker	ABour			
Visible Emission From Discharge Conveyor System	w			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			1		
Inspector:	Moland				
Date of Inspection:	19015				
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
Unit	Visual Inspection <u>NORMAL</u> or		Comr	ments	
Visible Emission From Shaker	ABNORMAL NOW COL			er gegente control con a companyante	
Visible Emission From Discharge Conveyor System	Namal	2			. n 1- 1- 2-

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS		Marie Control of the			
Inspector: Paul Carl					
Date of Inspection: 8-1-1	15				·
Shift: 1st Shift or Znd Shift	Time:	5:00 pm			
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments	
Visible Emission From Shaker	ABnor	Cepain	AND COMMAND TO		
Visible Emission From Discharge Conveyor System	Nor	1			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector:	Johand				
Date of Inspection:	30/5				
Shift: 1st Shift or 2nd Shift	Time:	P. 6000			
			Comr	ments.	
⊎nit	Visual				
	Inspection	120 mm 1 m			
	<u>NORMAL</u>	100 mm and 100 mm			
	or		and the state of t		
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge					
Conveyor System	Monnal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Damian Sali	nas J/			
Date of Inspection: 8-17-15				
Shift: 1st Shift or 2nd Shift	Time:	5m	Comments	
Unit	Visual Inspection			1900 - 19
	<u>NORMAL</u> or			
	<u>ABNORMAL</u>		<u> </u>	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge	Nov	_		
Conveyor System	/0/1			į.

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	and the second s		٦	
	linas Dr		4	
Date of Inspection: 8-18-15				
Shift: st Shift or 2nd Shift	Time:	5pm		
Unit	Visual Inspection NORMAL		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	Nor	gggggdarforming.		
Visible Emission From Discharge Conveyor System	Nor	And the second s		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
 characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIE	BLE EMISSION NOTATIONS						1
Inspe		2					4
Date	of Inspection: 8/19/15	Time:	<i>j</i>		and the state of t		1
Shift	1st Shift or 2nd Shift	Berlin Berlin School States) AM	Comin			:
	Unit	Visual Inspection		Marie de la companya		The state of the s	1
		<u>NORMAL</u> For #					· !
		ABNORMAL					ĺ
	ible Emission From Shaker	Non					
Vis	ible Emission From Discharge	Nac					
Ico	nvevor System	1.1010		t countin	ng start up ro shut down		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
- or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

	BLE EMISSION NOTATIONS Sector: Les Volces
C	of Inspection: 8 191 2015
5	2nd Shift
ACCOUNT OF THE	Unit Inspection Normal
	ABNORMAL AND ABNORMAL
	sible Emission From Shaker
	sible Emission From Discharge
	onveyor System S

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

	IBLE EMISSION NOTATIONS Dector:					
Dat	e of Inspection:	Time:	60 h ~		A CONTRACTOR OF THE STATE OF TH	
Shi	ft: 1st Shift or 2nd Shift	/ Visual	D-00 KV	-Com		
	CHIC	inspection de <u>NORMAL</u> s				
		ABNORMAL				y,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
ı	isible Emission From Shaker	Alsnor	repaire			
V	isible Emission From Discharge onveyor System	ror		not count	ing start up ro shut dow	1

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

	9						
12400	/ISIBLE EMISSION NOTATIONS			•			11
1	nspector: Huber	Molonel_			·		1
T	Date of Inspection: 8 20 20	012					
1	Shift: 1st Shift or 2nd Shift	Time: ¿	5.00 pm	Com	imenis		ŀ
	Unit "	www.wisual					
		Inspection INORMAL					
		ABNORMAL					1
	Shaker	A'BINOWANT TO SE					$\frac{1}{2}$
	Visible Emission From Shaker	Mormal				_	
	Visible Emission From Discharge	Domal					_
	Conveyor System				-l-ut down	n	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)







VISIBLE EMISSION NOTATIONS					
Inspector: Paul Lall					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	: 80 AN	ommenus		anna ann a leasann an
Unit	Wisval Inspection:				
	<u>NORMAL</u>				
	<u>ABNORIMAL</u>				
Visible Emission From Shaker	ABNOT				
Visible Emission From Discharge	NA				
Conveyor System				shut down	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





	ISIBLE EMISSION NOTATIONS						1
1	spector: Ruben Mola	mor——					•
D	Pate of Inspection: 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	S Time:	4 VV DIV		The state of the s		
s	hift: 1st Shift or 2hd Shift		<u> 500 n.</u>	Comu	menus		
30,000	Uniti	Wishedikin Inspedikin					
9(2) do (1)		<u>MORIMAL</u>					
		<u>ABNIORIMAL</u>					4
	Visible Emission From Shaker	Normal _					
	Visible Emission From Discharge	1 Samuel					
	Conveyor System	1 -0111 -00			un ro shut dow	n	

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
- or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6





VISIBLE EMISSION NOTATIONS Inspector:	War					THE PARTY OF THE
Date of Inspection: 8 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	15 Time:	5:00pm	The second secon			1
Shift: 1st Shift or 2nd Shift	Visitali Unspection			nincerner		
	<u>NORMAL</u> Of ABNORMAL					
Visible Emission From Shaker	Normal	SSAL I (rico-prose)				
Visible Emission From Discharge Conveyor System	Normal		in operation, not coun	ting start up ro shut d	lown	

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
- or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6





VISIBLE EMISSION NOTATIONS Inspector:	and III				
Date of Inspection: 8 32 3015	5	- 0.6			TOTAL STREET
Shift: 1st Shift or 2nd Shift	Time:	<u> </u>	Celn	nianciel©	
Unit	Medellon Medellon				
	NORMAL or				
in From Shaker	ABNORIVA	(1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Visible Emission From Shaker	2011112				
Visible Emission From Discharge	LEMIX				
ICONVEVOI SYSTEM				wart up ro shut d	OWII

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





				•
VISIBLE EMISSION NOTATIONS Inspector:				
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	on Con	nimenis	- Plant - Transition
Unit	Wisual Viscozetton	eri pinangan di kacamatan di kac Ngjaran		
	MORIMAL			<u> </u>
	AIBINIORIMAL .			(1.04) (1.04) (1.04)
Visible Emission From Shaker	96			
Visible Emission From Discharge				
Conveyor System			sting start up ro shut	down

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6







VISIBLE EMISSION NOTATIONS						1
Inspector: Ted Conty	<u> </u>				•	1
Date of Inspection: 8/25 //5	and the second s		•		and the state of t	iracioù
Shift: 1st Shift or 2nd Shift	Time:	50M	Ceiml	men4		
Unit	VIsual Jinspeation					
	<u>MORMAL</u> or					
	of <u>ABNORMAL</u>					\dashv
Visible Emission From Shaker	Nov					
Visible Emission From Discharge	Al-	%250 hassess was \$4 AMA on MARIE and CORRECT C	gen god 2000 ta eta eta Esta bere hilipida eta eta eta eta eta eta eta eta eta et			
Conveyor System	100			ing start up ro shut o	łown	

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6





\	ISIBLE EMISSION NOTATIONS	T				1", V.	
	nspector:	t your				`	
ļ	Date of Inspection: 8/26/15	Time:				1000000000000000000000000000000000000	,
-	Shift: 1st Shift or 2nd Shift		<u> 5000</u>	Comin	nents		
	Unit	Wisual 41 Inspection		Paris Communication (Communication Communication Communica			
		<u>INIOPIMIAL</u> (
,		ABNORMAL 3					
	Visible Emission From Shaker	Nol					į
	Visible Emission From Discharge			dd dd Cardler (dd Cyfriadd dd Arferd Cardler (dd Cardler Cardl			
\	Conveyor System	1 / V & L	<u> </u>	and sountil	ng start up ro shut down		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)







VISIBLE EMISSION N	OTATIONS						4
Inspector:	Ted C.	pton:				·	i
Date of Inspection:	1/27/15	Time:		-	·	THE WORKSTON OF THE STATE OF TH	
Shift: 1st Shift o	r 2nd Shift	Time:	5 9 M	Co	ommenis		
Unit		Visual Inspection	Carly many and a second	TO THE RESERVE OF THE PERSON O			
		<u>MORIMAL</u>				El an el anciente de la companya de	
		<u>ABNORIMAL</u> ()			5.5-77)		
Visible Emission Fro	m Shaker	Nov	ungs sign das enthalmen opprografisch verzonen dasse date deutweist gestellt der deutweist gestellt deutweis				
Visible Emission Fro	m Discharge	Nov		200 - 100 -			
Convoyor System		Gr. V			chii	t down	

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6





VISIBLE EMISSION NOTATIONS Inspector:					
Date of Inspection: 8/28/5					
Shift: 1st Shift or 2nd Shift	Time:	SPM	Comb	ineinis	
Unit	Visval Inspection				
	<u>MORMAL</u>				
	<u>ABNORMAL</u>			4.7	
Visible Emission From Shaker	Nor		and the second s		
Visible Emission From Discharge	·No	- MATERIA AND AND AND AND AND AND AND AND AND AN			
Conveyor System	1		t - aunti	ing start up ro shut d	own

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6







			_			
VISIBLE EMISSION NOTATIONS						
Inspector:	and and		-		•	*1
Date of Inspection: 8/29/15			-			= contractor l
Shift: 1st \$hift or 2nd Shift	Time:	50M	Con	nments		
Unit	Wisual **** n (hspeation) ***					
	<u>MORIMAL</u>					
	<u>ABNORIMAL</u>					
Visible Emission From Shaker	No	Tunanegarangconstant constanting in tragging and another recovers	ett sammen			
Visible Emission From Discharge		La constitution con anticipation con casa casa activa acti	Selection of Contract			
Conveyor System				ting start un ro shut	down	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





Date of Inspection: 8/30/15
Shift: 1st Shift or 2nd Shift Time: 60mmenus
Unit Visual Impedition : Normal
ABNORMAL
Visible Emission From Shaker Nov
Visible Emission From Discharge Conveyor System Volume of the control of the co

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

5 of 6







VISIBLE EMISSION NOTATIONS			1		
Inspector:	and on the same				
Date of Inspection: 8/3///	5				
Shift: 1st Shift or 2nd Shift	Time:			Coliniments	
Unit	Misual Inspection				
	<u>NORMAL</u> or				ni.
	<u>ABNORIMAL</u>				S. Indiana Co.
Visible Emission From Shaker	No	- November (1970) COS (NEW YORK)	troid the collection and compared the production and the collection of the collectio		
Visible Emission From Discharge	- n/		00000000000000000000000000000000000000		
Conveyor System	100/				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)